



INDEX**FIELD WELDING INSPECTION MANUAL**

<u>Section</u>	<u>Title</u>	<u>Page</u>
I	Opportunity and Use	3
II	Welding Process and Terminology	4
III	Essentials for an Inspector	11
IV	Welding Symbols	12
V	Inspector Duties	15
VI	Specifications for Welding Procedures	18
VII	Weldment Defects	21
VIII	Nondestructive Testing	34
IX	Welding Equipment	36
X	Inspector Responsibilities	38
XI	Additional Information and References	43

PREFACE

This manual is written to help meet a continuing and growing need among Inspectors whose common interest is to function as welding inspectors in addition to their other inspection duties. These inspectors function under the direction of the Resident Construction Engineers. Despite the wide diversity in training and background of these inspectors it becomes more evident each year that continued progress is increasingly more dependent upon technical review of the specifications.

With the increased use of the new higher strength steels it is even more important than ever before that better welding inspectors are needed to understand and to enforce the specifications so that the minimum design criteria are incorporated into the final structure.

Since welding is essentially a metallurgical operation it is best that the inspector understand a few of the basic fundamentals and the technology in applying this knowledge to obtain sound weldments. The illustrated procedures, inspection methods and data presented in this manual are for the inspector's beneficial study and to reinforce their periodic references to various welding problems.

All references are to the American Welding Society Specifications to the AWS D-1.5 and as modified by the Iowa Department of Transportation Standard Specifications and Supplemental Specifications.

SECTION I

Opportunity and Use

This manual outlines the inspector's duties and responsibilities for the proper inspection of weldments made under field conditions by approved welding processes. It is intended as an informational source for the inspection of methods and weldments.

It is the responsibility of the Engineer or the supervisor appointed by them to see that proper methods outlined in this manual are understood and applied to the respective work.

Most of the welding specifications are incorporated into this manual but the inspector may find particular instances where the plans will carry additional welding requirements, and in those cases the plans must at all times be followed.

There are at times, errors on the plans, especially on the use of welding symbols. Whenever there is reason to question a particular drawing the inspector should consult their engineer and have them verify it with the Office of Bridges & Structures in Ames.

SECTION II

Welding Processes and Terminology

Welding is a localized coalescence of metal wherein coalescence is produced by heating to suitable temperatures, with or without the application of pressure, and with or without the application of filler metal. The filler metal either has a melting point approximately the same as the base metal or has a melting point below that of the base metal but above 800°F.

Resistance welding is a form of welding that uses pressure but no filler metal. Manual shielded metal arc welding is a form of welding that uses a filler metal that melts at the approximate temperature of the base metal and uses no pressure. Brazing is a form of welding because the filler metal is always above 800°F and that soldering is not a form of welding because its filler metal is always below 800°F.


Pressure (Resistance) Welding

Resistance welding may be done with either alternating current or direct current. The type of current used will either be designated in the welding procedure specification or left up to the welder to decide for themselves.

Resistance welding can be seen on shear stud connectors on bridge beams. This type of resistance welding varies somewhat from others in that a flux tip is used on the stud plus a heat-resistant ceramic arc shield (ferrule). The flux tip acts as a de-oxidizer and arc stabilizer for the welding while the ferrule holds the molten metal in a prescribed area as the pressure is applied and coalescence takes place.

Non-Pressure Welding

Arc welding is one of the most common and widely known forms of welding in use today. It is not surprising to find that most of our problems deal with this type of welding, both in the field and in the fabricating shop. This manual is written for the sole purpose of inspection of arc welding and resistance welding done on the job site.



TERMINOLOGY

Air carbon arc cutting: An arc cutting process wherein the severing of metals is effected by melting with the heat of the arc and an air stream is used to facilitate the removal of the metal.

Arc blow: The swerving of an electric arc from its normal path because of magnetic forces.

Arc gouging: The application of arc cutting wherein a U-groove is formed.

Automatic Welding: Welding with equipment, which performs the entire welding operation without constant observation and adjustment of the controls by an operator.

Axis of a weld: A line drawn through the length of a weld.

Backing: Material (usually metal) backing up the joint during welding to facilitate obtaining a sound weld at the root.

Back weld: A weld deposited at the back of a single groove weld.

Bare Electrode: A filler metal electrode without a coating or covering other than that used for drawing the wire.

Base Metal: The metal to be welded or cut.

Bevel: A type of edge preparation.

Bead Weld: A type of weld composed of one or more string or weave beads deposited on an unbroken surface.

Blow hole: See gas pocket.

Butt Joint: A joint between two members lying approximately in the same plane.

Chamfer: The contour prepared on the edge of a member to be welded.

Crater: A depression at the termination of a weld bead.

Crater Crack: A crack in the crater of a weld bead.

Depth of Fusion: The distance that fusion extends into the base metal from the surface melted during welding.

Downhand: Position of welding wherein welding is done from the top side and the axis of the weld metal is horizontal.

Electrode: (Metal Arc Welding) Filler metal in the form of a wire or rod, either bare or covered, through which current is conducted between the electrode holder and the arc.

Faying Surface: That surface of a member, which is in contact with another member to which it is to be joined.

Filler Metal: Metal to be added in making a weld.

Flux: Material used to prevent dissolve or facilitate removal of oxides and other undesirable substances.

Flux Cored Arc Welding: An arc welding process in which the consumable electrode wire is hollow and is filled with flux material. Shielding may be from the solid flux only or from solid flux along with additional gas shielding.

Gas Metal Arc Welding: An arc welding process wherein coalescence is produced by heating with an electric arc between a filler metal (consumable) electrode and the work. Shielding, is obtained from a gas, a gas mixture (which may contain an inert gas) this process has sometimes been called Mig Welding.

Gas Pocket: A weld cavity caused by entrapped gas.

Heat-Affected Zone: That portion of the base metal which has not been melted, but whose mechanical properties or micro-structures have been altered by welding.

Interpass Temperature: In a multiple-pass weld, the lowest temperature of the deposited weld metal before the next pass is started.

Kerf: The space from which metal has been removed by a cutting process.

Manual Welding: Welding wherein the entire welding operation is performed and controlled by hand.

Notch Effect: An abrupt change of contour or section, or of a defect or imperfection in workmanship which causes high local concentration of stress and constraint against ductile action, thereby affecting structural behavior adversely. Such notch effects are especially detrimental to fatigue or impact strength, and resistance to brittle fracture.

Overlap: Protrusion of weld metal beyond the bond at the toe of the weld.

Oxygen Gouging: An application of oxygen cutting wherein a chamfer or groove is formed.

Parent Metal: Metal that is to be welded or cut.

Peening: The mechanical working of metals by means of hammer blows.

Porosity: Gas pockets or voids in metal.

Postheating: The application of heat to a weld or weldment immediately after welding.

Preheating: The application of heat to the base metal immediately before welding.

Pressure Welding: Any welding process or method wherein pressure is used to complete the weld.

Resistance Welding: A group of welding processes wherein coalescence is produced by the heat obtained from resistance of the work to the flow of electric current in a circuit of which the work is a part, and by the application of pressure.

Reverse Polarity: The arrangement of direct-current arc-welding leads wherein the work is the negative pole and electrode is the positive pole of the welding arc.

Root Opening: The separation between the members to be joined, at the root of the joint.

Root Face: That portion of the groove face adjacent to the root of the joints.

Root of Joint: The portion of a joint to be welded where the members approach closest to each other. In cross-section the root of the joint may be either a point, a line or an area.

Root of Weld: The point, as shown in cross-section, at which the bottom of the weld intersects the base metal surfaces.

Run-off Tab: Plates having the same joint preparation as the joint to be welded and placed on the end of the joint to carry the weld on past the end of the welded joint.

Semi-Automatic Arc Welding: Arc welding with equipment, which controls only the filler metal feed. The advance of the welding is manually controlled.

Shielded Metal-Arc Welding: An arc-welding process wherein coalescence is produced by heating with an electric arc between a covered metal electrode and the work. Shielding is obtained from the decomposition of the electrode covering. Pressure is not used and filler metal is obtained from the electrode.

Size of Weld:

- A. Groove Weld.** The joint penetration (depth of chamfering plus the root penetration when specified).
- B. Fillet Weld.** For equal-leg fillet welds, the leg length of the largest isosceles right triangle which can be inscribed within the fillet-weld cross-section.

Slag Inclusion: Non-metallic solid material entrapped in weld metal or between weld metal and base metal.

Spatter: The metal particles expelled during welding and which do not form a part of the weld metal.

Straight Polarity: The arrangement of direct-current arc-welding leads wherein the work is positive and the electrode is the negative of the welding arc.

Stringer Bead: A type of weld bead made without appreciable transverse oscillation.

Tack Weld: A weld made to hold parts of a weldment in proper alignment until the final welds are made.

Underbead Crack: A crack in the heat-affected zone not extending to the surface of the base metal.

Undercut: A groove melted into the base metal adjacent to the toe of a weld and left unfilled by weld metal.

Weave Bead: A type of weld bead made with transverse oscillation.

Weld Metal: That portion of a weld, which has been melted during welding.

Welder: One who is capable of performing a manual or semi-automatic welding operation.

Welder Certification: Certification in writing that a welder has produced welds meeting prescribed standards.

Welding Procedure: The detailed methods and practices, including joint welding procedures, involved in the production of a weldment.

Welder Qualification: The demonstration of welder's ability to produce welds meeting prescribed standards.

Welding Sequence: The order of making the welds in a weldment.

Weldor: See welder.

Weldment: An assembly whose component parts are joined by welding.

Weldment Defect: The failure of any weldment to meet the specifications.

SECTION III

Essentials

The inspector acts as the judicial representative of the Iowa Department of Transportation and it is their responsibility to judge the quality of the welding and workmanship in relation to the outlined specifications. Although the inspector must strive for the best quality he/she must not delay the contractor without just cause.

Welding Knowledge

While actual welding experience is valuable to an inspector it is not one of the necessary essentials. The inspector should have sufficient knowledge of the welding process to enable him/her to know what defects are most likely to occur. He/she should have a general knowledge of current settings and welding techniques. He/she must be familiar with the procedure specifications, and know how to apply them.

Knowledge of Test Methods

It is essential that the inspector have some knowledge of the test methods used by the Iowa Department of Transportation so a better understanding of why one welder may be qualified to weld and another welder is not. This knowledge also enables the inspector to understand the limitations that may be imposed on some welders.

SECTION IV

Welding Symbols

Welding symbols were formulated by the American Welding Society and have since been standardized for the entire welding industries. These symbols convey the requirement set forth by the designer in a given area to meet the calculated stress load that will be applied. It is therefore important that the inspector understand their meaning thoroughly, and apply it correctly at all times.

A table of the most commonly used symbols has been prepared for this manual.

STANDARD WELDING SYMBOLS

Basic Welding Symbols and Their Location Significance								
Flange	Groove							Location Significance
Corner	Square	V	Bevel	U	J	Flare-V	Flare-Bevel	
								Arrow Side
								Other Side
Not used								Both Sides
Not used		Not used	Not used	Not used	Not used	Not used	Not used	No Arrow Side or Other Side Significance

Typical Welding Symbols		
Slot Welding Symbol	Square-Groove Welding Symbol	Flare-V and Flare-Bevel-Groove Welding Symbols
Depth of filling in inches (omission indicates filling is complete)	Omission of size indicates complete joint penetration	Root opening
Plug Welding Symbol	Chain Intermittent Fillet Welding Symbol	Edge- and Corner- Flange Welding Symbols
Included angle of countersink	Pitch (distance between centers) of welds	Radius
Backgouging Welding Symbol	Back or Backing Welding Symbol	Surfacing Welding Symbol Indicating Built-up Surface
Second reference line used for back gouging and welding as a second operation	Any applicable single groove weld symbol	Size (height of deposit)
Flash or Upset Welding Symbol	Staggered Intermittent Fillet Welding Symbol	Single-V Groove Welding Symbol Indicating Root Penetration
No arrow side or other side significance	Pitch (distance between centers) of increments	Size
Spot Welding Symbol	Double-Bevel-Groove Welding Symbol	Projection Welding Symbol
Size (diameter of weld) Strength (in lb per weld) may be used instead	Arrow points toward member to be prepared	Projection welding reference must be used
Seam Welding Symbol	Double-Fillet Welding Symbol	Welding Symbols for Combined Welds
Length of welds or increments	Size (length of leg)	

Basic Joints—Identification of Arrow Side and Other Side of Joint		Process Abbreviations
Lap Joint	Edge Joint	
Other side member of joint	Arrow side of joint	Where process abbreviations are to be included in the tail of the welding symbol, reference is made to Table A, Designation of Welding and Allied Processes by Letters, of AWS 2.4-79, 71.
Arrow of welding symbol	Arrow of welding symbol	
Arrow side member of joint	Joint	
	0-30	

AMERICAN WELDING SOCIETY, INC.
550 N.W. LeJeune Road
P.O. Box 351040
Miami, Florida 33135

AMERICAN WELDING SOCIETY




Basic Welding Symbols and Their Location Significance								
Location Significance	Fillet	Plug or Slot	Spot or Projection	Seam	Back or Backing	Surfacing	Scarf for Brazed Joint	Flange Edge
Arrow Side								
Other Side						Not used		
Both Sides		Not used	Not used	Not used	Not used	Not used		Not used
No Arrow Side or Other Side Significance	Not used	Not used			Not used	Not used	Not used	Not used

Supplementary Symbols Used with Welding Symbols		
Convex Contour Symbol	Weld-All-Around Symbol	
Convex contour symbol indicates face of weld to be finished to convex contour	Weld-all-around symbol indicates that weld extends completely around the joint	
Finish symbol (user's standard) indicates method of obtaining specified contour but not degree of finish		
Joint with Backing	Joint with Spacer	Melt-Thru Symbol
With groove weld symbol	With modified groove weld symbol	Any applicable weld symbol
Note: Material and dimensions of backing as specified	Note: Material and dimensions of spacer as specified	Melt-thru symbol is not dimensioned (except height)
Flush Contour Symbol	Multiple Reference Lines	
Flush contour symbol indicates face of weld to be made flush. When used without a finish symbol, indicates weld without subsequent finishing	First operation shown on reference line nearest arrow	
	Second operation, or supplementary data	
Finish symbol (user's standard) indicates method of obtaining specified contour but not degree of finish	Third operation, or test information	
Field Weld Symbol	Complete Penetration	Location of Elements of a Welding Symbol
Field Weld symbol indicates that weld is to be made at a place other than that of initial construction	Indicates complete penetration regardless of type of weld or joint preparation	Finish symbol
		Contour symbol
		Root opening: depth of filling for plug and slot welds
		Effective throat
		Depth of preparation; size or strength for certain welds
		Specification, process, or other reference
		Length of weld
		Pitch (center-to-center spacing) of welds
		Field weld symbol
		Arrow connecting reference line to arrow side member of joint
		Weld-all-around symbol
		Reference line
		Elements in this area remain as shown when tail and arrow are reversed
		Tail (Tail omitted when reference is not used)
		Basic weld symbol or detail reference
		Number of spot or projection welds
		(BOTH SIDES)
		(ARROW/OTHER SIDE)
		(N)

Supplementary Symbols						
Weld-All-Around	Field Weld	Melt-Thru	Backing, Spacer	Contour		
Flush	Convex	Concave				

Basic Joints—Identification of Arrow Side and Other Side of Joint		
Butt Joint	Corner Joint	T-Joint
Arrow of welding symbol	Arrow side of joint	Arrow of welding symbol
Arrow side of joint	Arrow side of joint	Arrow side of joint
Other side of joint	Other side of joint	Other side of joint



SECTION V

Inspector Duties

The inspector's primary function is that of inspecting the contractor work and to see that it meets the requirements of the specifications. If the contractor should request advice on changes or modifications in any way the inspector should cooperate in every way possible to obtain this information from the proper authorities. However, if changes or modifications are approved it must always be with the definite understanding that the contractor has the full responsibility for the quality of the final product.

An inspector should keep in touch with the activities of the contractor personnel. Generally, the contractor does not intentionally disregard contract requirements. However, errors can occur through worker carelessness or lack of familiarity on the part of the contractor. While the correction of any errors remains the responsibility of the contractor, the inspector should make certain these mistakes are brought to the contractor's prompt attention. Early correction of a mistake can oftentimes produce a satisfactory product.

The inspector duties will follow the general headings below:

1. Interpretation of the Plans and Specifications
2. Verification of Welder and Procedure
3. Verification of Written Welding Procedures
4. Production Welding Checks
5. Keeping Records and Reporting

Interpretation of Plans and Specifications

The inspector should become familiar with the construction details pertaining to welding. Oftentimes notes on the plans will explain a welding detail or method of prescribed welding. It is also necessary to know any special provisions or proposal that may be specified in a particular contract document. These special provisions or proposals often carry the welding documentation that will require special treatments necessary to obtain a satisfactory weld.

The inspector should not accept responsibility for deviations until specifically authorized to do so. Many unknown stresses may be encountered when changes or deviations take place, which could affect the structure adversely.

Verification of Welder and Procedure

The specifications that apply to the making of weldments require qualification of the welder. The procedure to qualify these welders is specified in AWS and the Standard Specification. It is the inspector's duty to verify that each welder who works under these specifications has been properly qualified according to these specifications. The inspector must verify the test data and the results of the tests. Thus, one very important duty of the inspector is to see that the welder only works within the qualification limits. Since most field welders are qualified for only one year at a time, a requalification test is necessary to keep a welder's certificate updated at all times. Other limiting variables to be verified by the inspector are the types of weld, groove or fillet, the position to be welded and the thickness of the joint to be welded.

One specification of weldments is the requirement of a prescribed welding procedure. These welding procedures are prescribed for the type of joint to be used, and for the grade and thickness of the base metal to be employed for the work. These procedures are necessary to produce welded joints with acceptable mechanical properties in accordance with the specifications.

Before any welding is started the inspector should verify that the welding procedures have been established. For the most part the procedures required for field welding are set forth in the Construction Manual. These instructions include the necessary welding procedures for the various types of piling used. However, the diaphragms, deck plates, bearing plates and reinforcing are not covered in this manual.

It is also the inspector's duty to note if any changes in a welding procedure are in excess of the limits set out in AWS. When a modified procedure is necessary the inspector should be sure it is not used in the structure until it has had final acceptance by the Offices of Materials and Design.

Once a qualification procedure has been accepted or approved it will remain approved until one of the essential variables have been changed. These variables and their limits can be found in AWS.

Verification of Written Welding Procedures

The welding of some items has become so routine that they have become to be known as prequalified joints. These joints are of a basic design and the welding of them requires very little in the way of a written procedure. The inspector will find a list of these prequalified joints in the AWS book.

While some of these prequalified joints are basic fundamentals of a joint and for small weld areas, the same joint may be used in a bridge that will extend for the entire length of the structure. The more the length of any joint is involved in a procedure the more it becomes a mandatory requirement and its acceptance should be the responsibility of those people more familiar with welding problems. The field welding inspector should at no time take it upon himself/herself to accept a welding procedure but should be familiar enough with it to enforce it within the limits of the AWS specifications.

Not all welding procedures can be as simplified as the welding of piling instructions have been. However, certain basic ideas can and are simplified in AWS. Additional basic procedures will be outlined later in this manual.

Selection of Production Test Samples

Not very often does a specification call for production test samples of field welding, but it does happen on occasions and therefore the inspector must have an idea of what is expected in taking these samples. The specification will state if the production test is to be non-destructively tested. It will also state what type of non-destructive test is to be performed.

When non-destructive tests are to be performed it will usually be in the form of radiographic inspection. The number or frequency of radiographs to be taken will be included in the specification document. However, when spot radiographic inspection is called for the inspector may be required to make the decision of when the radiographic inspection is to be made. These tests may be made by chance or in accord with an established order. In either case the contractor and the state are definitely concerned about new welders and some early radiographic inspection is highly desirable, followed by less frequent inspection once the welder has proven their consistent ability.

Additional non-destructive testing may be performed by magnetic particle inspection, trepanning, ultra-sonic, dye penetrant, metallurgical examination, mechanical testing to destruction of run off tabs or other detailed examinations.

Records and Reports

Any work performed in the field that requires inspection or tests will also require records. However, required or not, an inspector should keep a good record of their work. This may be in the form of a set of notes or as detailed as the Resident Engineer requires.

It is also the inspector's duty to check all records for detailed accuracy, in accordance with the contract documents, and to have them available when required. Any records that may require a contractor's signature should be prepared by the contractor and not by the inspector.

SECTION VI

Specifications for Welding Procedures

Many factors contribute to the end result of any welding operation. Because of the complexity it is desirable and essential that the vital parts, associated with the welding of a joint, are properly detailed to permit a clear understanding of the intended weld to all concerned. Generally, welding procedures have to be proved adequate by either qualification tests or enough prior use and experience to guarantee dependability. The sole purpose of welding procedures is to describe the details that are to be followed in the welding of specific materials or type of joint.

Description and Details

The details of a welding procedure specification when written must be in accordance with the contract specifications and within good welding practice. They must be sufficiently detailed including welding sequence to insure welds that will satisfy the contract specifications.

Following is a list of details that are normally covered in a welding procedure specification for the shielded metal-arc process. Other welding processes may have some specification changes of varying degrees, and when used in the field a reference to AWS will most certainly be needed.

Welding Process - Shielded Metal-Arc

Filler Metal - Unless otherwise specified in the contract the electrodes shall be E-7016, E-7018.

Base Metal - ASTM A709, Grade 36, or 50 or 50 W structural steel; ASTM A-252 steel pipe; SAE 1010 steel pipe; SAE 1000 corrugated steel pipe; ASTM A500 or A501 steel tubing

Type of current -AC, DC reverse (electrode positive) or DC straight (electrode negative).

Joint Design - Single bevel (with backing) double bevel, square butt welds, or fillet welds, and the thickness of the base metal.

Welder qualification - Welder qualified by tests given by the Iowa Department of Transportation.

Preparation of Base Metal – For materials up to 4 in. (100 mm) thick a max surface roughness value of 1000 μ in. (25 μ mm) is permitted.

Joint Welding Design - Details that influence weld quality in terms of specification requirements such as; Welding the web first on H piling. These details help determine the soundness of welds, and influence the structural properties of the finished joint.

Welding Position - Such as flat, horizontal, vertical or overhead.

Preheat Temperature - Unless otherwise specified in the contract documents the preheat temperature shall be as specified in the AWS Bridge Welding Code. (See I.M. 560, the supplement to this I.M.).

Interpass Temperature - Equal to minimum preheat temperature at all times. Maximum temperature is not critical provided the heat input during welding is not excessive. However, if heat treated steels are used the maximum temperature will be found in the AWS Code or the contract documents.

Additional Details

Some additional details that may not be mentioned in the welding procedure specification but still have adverse effects on the welding joint are summarized in the following paragraphs.

The indiscriminate use of peening shall not be permitted. Peening can be very detrimental to a weld if not properly used. However, the inspector should not confuse the use of the chipping hammer with peening a weld. Chipping hammers are required for the cleaning of slag from a weld. A more detailed description of peening is covered later in this manual under Section (XI) Welding Metallurgy.

Excessive heat input during welding can also be detrimental to a weld. Therefore a controlled heat input is a must for a good weld. Cracks may result from welding processes involving large heat inputs. In the arc welding process the heat input is lowered by reducing the current or by increasing the travel speed while maintaining the same current level. This explanation then reveals to us that, the stringer bead is far superior to the weaving method in which the forward travel speed is drastically reduced while the current level remains constant.

When a weld is not completely satisfactory upon completion, local sections may have to be removed for repair. This shall be done by one or by a combination of the following approved processes; grinding, oxygen cutting, or air-arc gouging. These are the same methods that are permitted in preparing the joint for the first time. The repair weld shall be made by the same process and procedures as the initial weld

Non-destructive testing of field welds is not made unless called for in the project specifications or directed by the engineer. Visual inspection of the welding is normally all that is required to be done by the inspector.

Postheat treatment of welds on structures are sometimes performed by a heat treatment of annealing process in order to develop the required mechanical properties or dependability as required. While this does not apply to the ordinary field welding work there are occasions when it has been called for. When postheat treatment is necessary it shall be part of the procedure specification and the inspector will be required to make sure the temperature is within the limits specified by the use of temperature sticks.

Welding procedure specifications are usually called for on the contract documents and then established by the contractor. Procedures that have the same basic fundamentals have been deemed as prequalified by the AWS and the essential variables have been outlined in the Construction Manual by the Construction Department. In this way definite welding procedures have been established for the welding of piling and all contractors follow the same procedures.

SECTION VII

Weldment Defects

Weldment defects can be classified into three groups:

1. Drawing or dimensional variations.
2. Structural discontinuities within the weld.
3. Physical or chemical properties of the weldment.

Drawing or Dimensional Defects

The making of satisfactory welds in regard to dimensional defects depends upon keeping within the specified dimensions for the size and shape of welds and the finished dimensions of the product. Departure from the dimensions in any respect should be regarded as dimensional defects and must be corrected before the final acceptance of the weldment can be made. Defects of this nature may be further subdivided as follows:

A Incorrect Joint preparation:

Established welding procedures require proper joint dimensions and preparation for each joint according to the thickness of the material being welded. The failure of an inspector to require these criteria may result in a greatly increased tendency to produce the weld defects listed under structural discontinuities within the weld. Therefore it is very important that all joint preparations are the same as shown in the specifications. (see Figure 1)

B. Incorrect weld profiles and sizes:

The profile of a finished weld can have a considerable effect upon its performance under load. The profile of one layer of a multipass weld can have an effect on the next pass in that it may cause slag inclusions or incomplete fusion to occur between the passes. Requirements concerning these defects are in AWS under the article entitled Weld Profiles and the inspector should have a good working knowledge of them. Failure to conform to these requirements constitutes a weld defect. Permissible tolerances and corrections for these various defects will also be found in AWS under articles "Quality of Welds", article 9.21 and Repairs article 3.7.

Overlap is a condition, which tends to produce notches, which are dangerous, due to the resultant concentrated stress under load. It is considered defective welding because the effective size of the fillet is reduced. It is also very hard for an inspector to be sure of the true fillet size, since the true size is governed by inscribing an isosceles right triangle inside the fillet weld cross section. Overlap is generally caused by improper welding technique or by improper electrical conditions. The inspector should look for overlap conditions primarily on the lower leg of fillet welds, but it can also be found at times on the last pass, or reinforcement pass of groove welds. (See Figure 2.)

Excess convexity, like overlap, tends to produce notches. What has been said about overlap is also true of excessive convexity. Excess convexity is also harmful in the case of an intermediate pass in a multi-layer groove weld, because slag inclusions or incomplete fusion can occur on a succeeding pass if corrective measures are not taken. (See Figure 3.)




Figure 1




Figure 2




Figure 3




Figure 4

Excess concavity is usually associated with fillet welds. The actual strength of such welds is less than that of a standard size weld since its throat thickness is less than normal when measured by the length of the fillet leg. This condition is usually caused by excessive welding currents or arc lengths.

Excessive weld reinforcement is also undesirable in that it tends to stiffen the section and establishes notches that help create undesirable stress concentrations. (See Figure 4.)

C. Incorrect final dimensions:

All weldments are fabricated to meet a plan dimension. The inspector and the welder must be aware of how much shrinkage can be expected at each weld joint and how much warpage will occur in the joint.

If the inspector visualizes the welding of a simple V on a simple plate and knows that the welding heat causes shrinkage in each pass, then they can also visualize the ends of the plate curling up. These heat shrinkage stresses will tend to produce cracking.

On welds that are designed to prevent shrinkage and warpage or welds that are restricted by manual devices it is obvious that while shrinkage must still occur it is restricted and thus produces shrinkage stresses that will tend to produce cracking.

The inspector should review the drawings to determine which dimensions are critical and then discuss the weldment dimensions and tolerance with the welder so he/she will devote major efforts to these critical areas. (See Figure 5.)

Structural Discontinuities

When making manual shielded metal-arc welds, various types of defects may occur. These defects can be classified as structural discontinuities and consist of porosity, slag inclusions, lack of fusion, cracks etc. This terminology is used here to denote an interruption in the soundness in weld metal itself and not change in the metallographic structure of the metal such as laminations, scabs etc.

Porosity is gas pockets or voids in the weld metal which are free of any solid materials, such as slag. It is formed as a result of gases driven from the weld metal during solidification of the weld. Porosity is generally classified into different groups as follows: scattered, clustered and linear.

Scattered porosity occurs throughout the weld metal and the voids may vary in size from microscopic to slightly over 1/8 in.(3 mm). (See Figure 6.)

Clustered porosity occurs in groups and may generally be associated with a change in welding conditions. (See Figure 7.)

Linear porosity occurs throughout the length of a weld and the voids are in a line with respect to the axis of the weld. This type of porosity generally comes in the root pass and usually can be traced to the inadequate preparation of the joint. (See Figure 8.)

The causes of most types of porosity can be controlled by avoiding the use of excessive currents and excessive arc lengths, the removal of rust prior to welding and proper preparation of the joint.






Figure 5




Scattered
Porosity

Figure 6



Clustered
Porosity

Figure 7



Linear
Porosity

Figure 8

Slag inclusions are entrapped non-metallic solids in or near the weld metal and vary in size and location. Slag in molten weld metal will rise to the surface unless restrained by another force. When welding by any of the metal-arc processes slag or gas may be formed or forced below the surface of the molten metal by the stirring action of the electric arc. Slag can also flow ahead of the arc and thus cause metal to be deposited over it.

Slag can also form on a root pass of a V weld if the root opening is too small to permit the arc to heat the bottom of the recess to a high enough temperature to allow the slag to float to the surface. (See Figure 9) The welder can create similar conditions to this by having undercutting or excessive convexity in a weld bead, or using too large an electrode in the root pass. This type of slag inclusion is elongated and usually of considerable size and thus the strength of the joint is reduced considerably.

When slag is forced into the molten metal or is formed by chemical reaction, its appearance is the same as porosity on a radiographic film. Slag of this type is most likely found in overhead welding.

The inspector should realize that most slag can be prevented by the welder using good sound welding practices, such as: Proper preparation of the groove before each weld bead is deposited. Use care to correct contours that are outside specifications and the use of preheat to retard the weld metal solidification.

In making multiple pass welds the slag from the center of the pass is easily removed but the edges are usually more difficult. This slag area is often referred to as bond-line slag. In most cases this slag can be re-melted and rise to the surface in the next pass but it can also remain and will show up in a radiograph as elongated slag at the bond line. The welding inspector should use good judgement on this part of the inspection in seeing that the welder does a good job of removing the slag between passes but that a tiny amount of slag left at the bond line should work out during the next welding pass.

Where a welder does an imperfect job of slag removal and another welding pass is put down over it, the slag will tend to interrupt the arc and fusion of the weld metal is prevented along with the re-melting of the old slag. The inspector will find the result of this as scattered slag inclusions.

Incomplete fusion is another structural discontinuity of which the inspector must be aware. Incomplete fusion is sometimes referred to as lack of fusion. Actually, it is best described as the failure of weld metal to fuse to a base metal or other weld metal and may occur at any place in a weld. The cause for lack of fusion is due to the failure of raising the temperature of the base metal to the fusing point or the failure to dissolve by fluxing, the oxides or other foreign material on the surface of the metal to be welded. Since the field inspector does not have the use of radiographic or ultrasonic inspection, the best inspection for incomplete fusion is by ascertaining the surfaces to be welded are free of all objectionable material. (See Figure 10.)

Most lack of fusion due to inadequate joint preparation is due to a heat transfer condition at the root of the joint rather than a failure to dissolve or flux surface oxides. When the portion of the base metal closest to the electrode is a considerable distance from the root the heat transfer will have to be made by conduction, which may be insufficient to attain the fusion temperature at the root. An unfused root area is undesirable in that the unfused area permits stress concentration that could cause failure without appreciable deformation due to reduced section area. Even though the working stresses in the structure may not involve tension or bending, at some pile splice welds the shrinkage stresses can cause a crack to initiate at the unfused area. Such cracks may progress as additional weld layers are deposited until they extend through the entire thickness of the weld. The inspector's vigilance at the time of the joint preparation and assembly is the best protection he/she can give to prevent lack of fusion at the root area. However, this does not mean the inspector should not watch out for other elements that also can cause lack of fusion such as too large of electrodes, high rate of travel or the use of insufficient welding current.

The term, undercut, is used primarily to describe the reduction of the base metal thickness at a line where the last bead of weld metal is fused to the surface or at the toe of a weld. It can occur on both groove and fillet welding but is most frequently found on the vertical leg of a horizontal fillet or the top side of a horizontal groove. Undercutting of both types is usually due to a technique employed by the welder, although magnetic arc blow can also be a factor. Undercutting can be detected by visual inspection and a tolerance for it has been set up in the AWS under the article entitled Weld Profiles. (See Figure 11.)

Cracks in welded joints are results of a localized stress that at some point has exceeded the ultimate strength of the material. Materials that have good ductility under a single stress have been known to fail with little deformation under a multi-directional stress system. As discussed before, the unfused area of the root may result in cracks. Any material that is hard or brittle is more subject to cracking than a ductile one, therefore it is important that the inspector makes certain the right and properly cared for electrodes are used. The ability of weld metal to remain intact during the welding operation is due to the composition and structure of the weld metal. Once a crack has started it will continue through additional layers of weld metal as deposited unless it is repaired before additional layers are made.


Known causes of cracks are: The wrong use and manipulation of electrodes, improper electrical conditions, travel speed and lack of preheat.

Different type of cracks are: Transverse, longitudinal, crater and base metal. The first three types are usually visible cracks that are easily found. The base metal cracks are much more difficult and test methods may be required to discover them. Like the name implies, the cracks are in the base metal and sometimes are under the weld bead. (See figure 12.)

Crater cracks are small and usually star-shaped and found in the weld crater itself. They start at the center of the crater and extend out to the end. Crater cracks are not detrimental to the weld metal if they are repaired. However, these may be starting points for longitudinal weld cracks when left unrepaired.


Various types of surface irregularities may occur during welding. These irregularities can vary from actual holes in the weld to surface roughness of the metal or excessive spatter. Improvement of these conditions is usually obtained by changing the electrical conditions. It is important to remove the cause of these irregularities because they can cause slag entrapment. In high quality welding it is not safe to assume that these irregularities will fuse out during the placement of the next weld bead. Good welding practice dictates their removal by grinding or chiseling.

The surface appearance of the weld generally reflects the ability and experience of a welder. The more uniform the weld bead surface the better the eye appeal. Good welding that is poorly finished should not be excused except under unusual conditions even though the integrity of the job is beyond question. Such unusual conditions would be a great magnetic disturbance at the location of the weld. At times piling are driven too close to the ground for splicing and the welder has to bend over or lie down in order to make the splice.







Inadequate Joint Preparation

Figure 9




Incomplete Fusion

Figure 10



Undercutting on Groove and Fillet Welds

Figure 11



Various Types of Weld Metal Cracks

Figure 12




Figure 13

Physical and Chemical Properties of Weldments

The physical and sometimes chemical properties are required on all weld metal. The properties are dependent upon the specifications involved. Any departure from these specifications must receive the approval of the Engineer. The AWS D1.5 Bridge Welding Code specifies the type of electrode that must be used for weldments.

Every six months, the Office of Materials publishes a current list of approved electrode certifications and furnishes a list of these manufacturers and the electrode types as changes occur, to each of the Transportation Center Materials offices and the Ames Office of Construction. The welding inspectors should refer to the list periodically to assure themselves that the welder is using an approved electrode from an approved manufacturer.

Methods of Testing

Various methods of testing are available to a weld inspector in a fabricating shop, but to a field weld inspector, the best inspection must be made by visual inspection and at best a few accessories such as gauges or a ruler. The following table has been set up for an inspection guide. Since radiographic inspection of field welding is rarely specified the field inspector's substitute is a periodic close observance of the welder's technique.

Tests for Welds

Defect	Methods of Testing
DIMENSIONAL DEFECTS	
Warpage	Visual inspection with proper mechanical gauges.
Incorrect joint preparation	Visual inspection - Comparison with workmanship sample.
Incorrect weld size	Visual inspection with proper mechanical gauges.
Incorrect weld profile	Visual inspection with proper mechanical gauges.
Incorrect final dimensions	Visual inspection with proper mechanical gauges.
STRUCTURAL DISCONTINUITIES	
Porosity	Radiographic - Magnetic Particle - Ultrasonic.
Slag Inclusions	Radiographic - Magnetic Particle - Ultrasonic.
Incomplete fusion	Radiographic - Magnetic Particle - Ultrasonic.
Inadequate joint penetration	Radiographic - Magnetic Particle - Ultrasonic.
Undercut	Visual inspection
Cracks	Visual inspection - Radiographic - Magnetic particle
Surface	Visual inspection - Comparison with workmanship sample.

SECTION VIII

Nondestructive Testing

The purpose of nondestructive testing is to detect weld discontinuities in weldments without impairing the usefulness of the material. There is an increasing growth in the use and types of testing available to the inspector. Currently, the methods accepted for weld inspection are visual, magnetic particle, liquid penetrant, radiographic, ultrasonic, eddy-current and leak and proof test techniques.

Under any one circumstance, one of these methods may be more suitable for that purpose than any one of the others.

Most nondestructive testing is expensive in that the operator of the equipment must be thoroughly trained and acquainted with the theory and application of the equipment. Therefore, the Design Department tries to eliminate any field welding in critical areas as much as possible and thereby relies on visual inspection for the majority of its field welding.

Visual Inspection

The visual inspection of weldments is of the first order of importance even when radiographic or other nondestructive means of testing is specified. It is the most important part of quality control. Visual inspection is also the most informative with regard to the general conformity of the weldment to specifications. It is the most extensively used of any method of inspection.

Visual inspection can be divided into four titles: Inspection skills, inspection before welding, inspection during welding and inspection after welding.

Skill

The field inspector should develop a definite procedure to insure adequate coverage of the various steps of welding. They must be familiar with the welding specifications, workmanship and all phases of welding.

Before Welding

Details to check before the welding starts are:

1. The material to be welded
2. Welder Qualification Certificate
3. Welder equipment and electrodes
4. Correct bevel and smoothness of edge preparation
5. Root opening
6. Clearance of backing strip or ring
7. Overall alignment and fit up
8. Welding procedure

During Welding

Details to check during the welding are:

1. Preheat and interpass temperature
2. Cleaning, chipping, grinding or gauging
3. Structural discontinuities
4. Postheating temperature when specified

After Welding

Details to check after the welding are:

1. Dimensional accuracy of the weldment.
2. Conformity to drawing requirements.
3. Acceptability of welds with regard to appearance.
4. The presence of any unfilled craters, undercuts, cracks, overlaps.
5. Postheating temperature when specified.

Summary

Visual inspection is invaluable as an inspection method but caution must be used in drawing conclusions. The inspector should not judge a good surface appearance in itself as high weld quality, but rather base judgement on evidence afforded by observations made prior to and during the welding along with the good weld appearance.

Gauges and workmanship samples are also useful to the inspector and he/she should familiarize themselves in their use. Gauges can be readily made from a thin piece of sheet metal or cardboard if necessary. Figure 13 gives the basic dimensions necessary for simple gauges.

SECTION IX

Welding Equipment

Most field welding machines are portable, that is, they are on a truck and can be moved around. The welding machine is usually a generator driven by a gasoline-powered engine and puts a DC current that may be reversed by changing the leads. The welding machine must contain a gauge or some means of determining the amperage output along with some method of increasing or decreasing the amperage as desired. The leads shall be in good condition with unfrayed connections at both ends.

Good quality electrodes are a must. Welding manufacturers produce good quality electrodes that conform to the AWS test requirements, however, this does not ensure their good quality when delivered to the job site. The welder should discard any damaged electrodes. When using low hydrogen electrodes, he/she must furnish them from undamaged hermetically sealed containers and have an oven for maintaining their dryness.

The welder's cleaning tools should consist of a chipping hammer and a wire brush. A cold chisel and a hammer may be substituted for the chipping hammer.

A cutting torch must also be available for cutting, beveling and fitting up of the joints of field welds when required. A grinder is also necessary for smoothing out rough cuts and for the removal of a bad weld. Few welders are so skilled with a torch that grinding is not necessary.

The welder must have knowledge of the joint to be welded. Before welding, the inspector should check this knowledge against the information furnished to the Resident Engineer and make certain that it conforms to requirements outlined in these instructions.

The welder is also responsible for being able to verify that he/she has a valid Iowa Department of Transportation welding certificate.

Permissible Length of Welding Leads

Wire	Size	Diameter of Each Wire – Mils	No. of Strands	Maximum (permissible) Length of cable -feet
1/0	0	74.5	19	100 ft. (30.48 m)
2/0	00	83.7	19	150 ft. (45.72 m)
3/0	000	94.0	19	225 ft. (68.58 m)
4/0	0000	105.5	19	300 ft. (91.44 m)

Typical Current Ranges for Electrodes in Amperes

3/32 in. (2.38 mm)	65-110	70-100	-
1/8 in.(3.18 mm)	100-150	115-165	140-190
5/32 in.(3.97 mm)	140-200	150-220	180-250
3/16 in.(4.76 mm)	180-255	200-275	230-305
7/32 in.(5.58 mm)	240-320	260-340	275-365
1/4 in. (6.35 mm)	300-390	315-400	335-430
5/16 in.(7.94 mm)	375-475	375-470	-

Temperature Sticks

Fahrenheit Temperature Sticks by Tempil are available as follows:

6° increments	100°-350°	50° increments	650°-900°
2°-13° increments	350°-500°	Approx. 25° increments	900°-1050°
5° increments	500°-650°	50° increments	1050°-2500°

SECTION X

Inspector Responsibilities

Under Section V the duties of the inspector were described in a general way but detailed inspection was not spelled out. In Section VII a detailed list of items was given as a check list for the inspector. It is now possible for the inspector to be familiar with the inspection required and be able to follow the instruction in **this IM** with a sense of responsibility.

Consultation with the welder is one responsibility the inspector should take care of as soon as it is known who the welder is going to be. If a visit with the welder before he/she comes on the job is possible, this is even better than a discussion after their arrival. After having checked their certificate, the class and polarity of the electrode should be discussed along with the proper preheat and interpass temperature. Consult with them on the need for proper joint preparation and fit-up. Give their first joint special attention so that caution will be used throughout the job.

Welding of Piling

The most important part of Highway field welding is the welding of piling and this entire manual is primarily devoted to welding the various types that are used. A description of the various types of piling and the welding is well defined **on page 42 of this IM**. The inspector who follows the procedures outlined in the instructions will be able to carry out the inspection duties with great care. See Appendix A.

Welding of Shear Stud Connectors

Stud welding must comply with AWS D1.5 section 7. Only studs with a qualified stud base may be used. Those currently approved are listed in M 453.10, Appendix A. Any other brand must submit their qualification tests to the Iowa Department of Transportation, Office of Materials, in Ames for approval.

A certificate of the studs used is required and shall be as outlined in AWS D.1.5 paragraph 7.3.3.

Operator Qualification: The first two stud shear connectors welded on a member, after being allowed to cool, shall be bent to a angle of 30 degrees from their original axes by striking the studs with a hammer. If failure does not occur in the weld zone of either stud the operator shall be qualified. If failure occurs in the weld zone of either stud, the procedure shall be corrected and two more studs shall be welded to the member and tested. If either of the second two studs fails, additional welding shall be continued on separate plates until two consecutive studs are tested and found to be satisfactory. Two consecutive studs shall then be welded to the member, tested, and found to be satisfactory before the operator is found to be qualified. The inspector shall then document the test in their file with the name of the operator and date of test. Qualification of each operator must be documented at the start of each project.

Welding shall not be done when the temperature of the base metal is below 0°F (-18°C) or when the surface is wet or exposed to rain or falling snow. When the temperature is below 32°F (0°C) one stud in each 100 studs welded shall be tested in addition to the first two tested.

The inspector shall allow only two studs to be initially installed to each bridge member. After these studs have been allowed to cool, the inspector shall have them bent to an angle 30 degrees from their original axis by striking the studs with a hammer. If failure occurs in the weld zone of either stud the weld procedure shall be changed and two more studs welded and tested as above. If either of the second two studs fail, additional welding shall be continued on separate plate until two consecutive shear studs are tested and found to be satisfactory. Two consecutive studs shall then be welded to a member, tested, and found to be satisfactory before any more production studs are welded to the bridge member.

The foregoing testing shall be performed after any change in the weld procedure (e.g., voltage change, amperage change, etc).

After the studs have been welded to the bridge member a visual inspection shall be made and each stud shall be given a light blow with a hammer. Any stud which does not have a complete end weld (360° fillet), any stud which does not emit a ringing sound from the light hammer blow, any stud that has been repaired by welding or any stud which has less than normal reduction in height due to welding, shall be struck with a hammer and bent 15° from the correct axis of installation, and in the case of a defective or repaired weld, the stud shall be bent 15° in the direction that will place that defective area of the weld in the greatest tension. Studs that crack either in the weld or the shank shall be replaced.

Studs that are to be replaced for reasons cited above or because they have otherwise been rendered unacceptable may be repaired by adding a 5/16 in. (8 mm) minimum fillet weld in place of the missing weld. The shielded metal arc process with low hydrogen electrodes, 5/32 in. (4 mm), or 3/16 in. (5 mm) in diameter shall be used in accordance with the AWS code. The repair weld shall extend at least 3/8 in. (10 mm) beyond each end of the discontinuity being repaired. Whenever the shielded metal arc process is used the AWS minimum preheat and interpass temperature table 4.4 applies. (See IM 560, the supplement to this IM.)

Studs that have failed the test shall be removed and replaced as follows. The replacement area must be determined as to tension or compression and the repair shall be made as follows. In members subject to tensile stresses the stud shall be removed and the area ground smooth and flush. In the area where base metal has been pulled out with the stud it shall be filled by the shielded metal arc process using low hydrogen electrodes and a qualified welder. After filling of the base metal the entire area shall be ground smooth. In members subject to compression stresses and the failure is above the fillet weld a new stud shall be welded adjacent to the defective one. When base metal is pulled from such area the repair shall be the same as for the tensile stress area except when the depth of defect is not more than the lesser of 1/8 in. (3 mm) or 7% of the base metal thickness the defect may be faired by grinding in lieu of filling the defective area with the weld metal. Where a replacement stud is to be placed in the defective area, the above repair shall be made prior to welding the replacement stud. Replacement studs shall be tested by bending to an angle of 15° from their original axis.

Longitudinal and lateral spacing of studs with respect to each other and to edges of beam or girder flanges may vary a maximum of 1 in. (25 mm) from the location shown on the drawings provided the adjacent studs are not closer than 2 1/2 in. (64 mm) center to center. The minimum distance from the edge of the stud base to the edge of a flange shall be the diameter of the stud plus 1/8 in. (3 mm) but preferably not less than 1 1/2 in. (38 mm).

WELDING FOR SUPPORTING FLOOR FORM JOISTS AND FINISHING MACHINE RAILS

Unless otherwise authorized by the engineer, any welding to the top flange of steel members for supporting floor form joists and finishing machine rails will not be permitted. Welding of hangers and supports to shear studs will be permitted as follows:

1. The welder must be certified and use low hydrogen electrodes and proper preheat.
2. No welding shall be permitted when the ambient temperature of the air is below 32°F(0°C) or when the lowest temperature during the preceding 12 hours has been below 0 °F(-18°C).
3. Windbreaks or shields shall be provided when the wind chill factor is strong or cold enough to prevent welding from being carried out in a normal manner without such protection.
4. Welding shall not be permitted on surfaces that are wet or exposed to snow.
5. Arc strikes on bridge flanges must be prevented at all times.

WELDING OF DIAPHRAGMS

Cleaning and Removal of Paint, etc.

On a bridge with a super-elevated curve the diaphragms are sometimes welded in place rather than bolted. The Office of Design has used this method because of the variable location of each diaphragm. Since the diaphragms do vary in location, some paint on the girder is usually where the diaphragm should be and therefore must be removed. The method for removing the paint may be by any of the following methods: blasting, paint remover or burning. If either paint remover or burning is used a good stiff wire brushing must also be used for final cleanup. When the paint remover method is used a great deal of care must be exercised so no slopping or spilling on other areas takes place, therefore the other two methods are preferred.

Undercutting

The welding of a diaphragm consists of fillet welding in the horizontal, vertical and overhead positions (2F, 3F, & 4F). Since undercutting can occur in any of these positions the inspector should watch for it closely. The tolerance for permissible undercutting is outlined in AWS D1.5, Section 9. The maximum permissible size of electrode for making fillet welds is outlined for manual shielded metal arc welding. The maximum size fillet weld, which may be made in one pass, shall be 5/16 in. (8 mm) in the horizontal or overhead position or 1/2 in. (13 mm) in the vertical position. In welding in the vertical position the progression of all passes shall be upward. These rules are also outlined under Article 4.6 in AWS D1.5.

Excessive Convexity

The convexity of a fillet weld profile shall not exceed 0.07 times the actual face width of the weld or individual bead, respectively plus 0.06 in. (1.5 mm) AWS D1.5 (Figure 3.3). All excessive convexity and overlap fillets are to be corrected. Corrections for various types of defects are covered in AWS D1.5 Article 3.7 and 9.25.

Welding of Railroad Bridge Deck Floors

Railroad bridges that span highways are designed with a steel deck that covers the bridge and are welded together in the field. The special provisions that accompany railroad bridge lettings usually specify that a welding procedure be submitted for the field welding of the deck.

The welding procedure for the steel deck must not only cover the design of the welding joint, but it must also cover the sequence of welding. This welding procedure should receive the approval of the Office of Materials before welding is permitted.

Since railroad steel bridge decks vary in length, width and type of steel used it is somewhat difficult to have a standard welding procedure and sequence to cover them. Basically, all the requirements necessary for qualifying the procedure and sequence are in AWS under Section 2, 3 & 5. The field inspector should understand the welding procedure and sequence thoroughly so he may help direct the welder in following the proper steps necessary.

Steel bridge decks involve longitudinal and transverse groove welds made in the flat position and are usually on plates of 1/2 in. (13 mm) thickness. Since welding is in both directions a multi-directional stress system can be built in if the procedure and sequence are not properly followed.

Welding of Reinforcing Steel

The welding of deformed reinforcing steel is not permitted without the approval of the Structural Materials Engineer. The welding or tack welding of deformed reinforcing steel is detrimental to the mechanical properties of the bar, unless a special welding procedure with proper preheat and interpass temperature has been established according to the carbon and manganese content of the bar. Any field inspector who discovers welding on deformed reinforcing bars should notify their superiors, or with their permission, contact either the Structural Materials Engineer.

When the welding of deformed reinforcing steel is permitted it is part of the specifications or at a location where the stresses of the steel is nil or at a minimum.

SECTION XI

ADDITIONAL INFORMATION AND REFERENCES

Welder Qualification

When a welder is tested for ability, it is conducted by the field Materials Office. These field inspectors issue the test plates and instruction to the welder, witness the welding of the plates and fill out the necessary forms. The machining, testing and reporting is done by the Office of Materials.

A copy of the instructions to field welders is included in this manual as additional information for the field construction inspector. While these instructions are for the welder they may also be helpful to field welding inspectors.

REFERENCES

The American Welding Society (AWS) has published several books on welding. Following is a list of books that are available from the Office of Materials in Ames, Iowa.

Filler Metal Specifications:

- A5.1-91 Mild steel Covered Arc-Welding Electrodes
- A5.5-96 Low Alloy Steel Covered Arc-Welding Electrodes
- A5.10-92 Aluminum and Aluminum Alloy Welding Rods and Bare Electrodes
- A5.15-90 Welding Rods and Covered Electrodes for Welding Cast Iron
- A5.17-97 Bare Mild Steel Electrodes and Fluxes for Submerged - Arc Welding
- A5.18-93 Mild Steel Electrodes for Gas Metal - Arc Welding
- A5.20-95 Mild Steel electrodes for Flux-Cored Arc Welding
- A5.23-97 Bare Low-Alloy Steel Electrodes and fluxes for Submerged Arc Welding
- A5.28-96 Low Alloy Steel Filler Metals for Gas Metal Arc Welding
- A5.29-98 Low Alloy Steel Electrodes for Flux Cored Arc Welding

Welding Handbook:

- Volume 1, Fundamentals of Welding - 1989
- Volume 2, Welding Processes - 1991
- Volume 3, Materials and Applications – Part 1

Welding Inspection - 1968

Resistance Metallurgy - 1966

Brazing Manual - 1963

Soldering Manual - 1964

Electroslag Welding – 1962

SPLICING PILE

Welding Steel Pile

Specification 2408.13 requires that all welds conform to the Structural Welding Code ANSI/AWS D1.1 of the American Welding Society.

A. Field Welding

All welding must be done by a state-certified welder. When the Office of Materials qualifies a welder, a certificate is issued showing the types of welds, which they are qualified to perform. Inspectors should ask to see the welder's certificate, and note: (1) certificate number, (2) date issued, and (3) qualified positions on the Log of Piling form. Certificates are good for one year and must be renewed annually, except requalification will only be required every two years for field welder who have successfully passed their qualification tests without failure for three consecutive years.

Welding and repair shall be done in accordance with Welding Procedure Specifications (WPS).

Only Shielded Metal Arc Welding (SMAW) and/or Flux Cored Arc Welding (FCAW) will be permitted for welding steel piles. Filler Metal shall be in accordance with the requirements of AWS Specifications. For SMAW, low hydrogen electrodes shall be used.

The welding electrode must be on the approved list published by the Office of Materials semiannually or be specifically approved by the Office of Materials.

Welding electrodes shall be kept dry and protected from moisture and humidity during storage and/or use.

Surfaces to be welded and surfaces adjacent to the weld shall be cleaned with a grinder or a wire brush and shall be dry and free of scale, slag, rust, moisture, grease and any other foreign material that would prevent proper welding.

B. Shell Pile

Shell pile manufactured by Union Metal requires splices to be fillet welded. The fillet weld should be equal in size to the thickness of the shell wall. The pile extension must be telescoped into the pile to be extended a minimum of 150 mm (6 inches). For splicing pile manufactured by Armco, a butt joint and square groove weld must be used as shown in Figure A, Appendix 11-4 of this IM.

C. Pipe Piles

Pipe pile may be extended using Figure A, or B, or C (Appendix A of this IM) depending on wall thickness and pile position at the time of splicing.

D. Steel H-Piles

Specifications require that field extension of Steel H-piles shall be made only by approved welding procedures involving the use of backing plates. Steel H-piles are extended with a butt joint requiring a single-bevel groove weld when welded in the horizontal position (Figure B, Appendix A of this IM) and a vee groove weld in the flat position (Figure C, Appendix A of this IM). The backing plate must be at least 6 mm (1/4 inch) thick, 38 mm (1 1/2 inches) wide and of the required length to extend full width of web and flanges. Note: HP 360 mm x 174 kg (HP 14 x 117) steel H-piles require a special welding procedure due to flange thickness.

If a backing plate thickness of more than 10 mm (3/8 inch) is used, weld the backing plate all around with a fillet weld. A backing plate 6 mm to 10 mm (1/4 to 3/8 inch) thick may be tack welded in place. Backing plates must be bent or ground to fit snug against the flanges, web, and have chamfered corners to fit between the flanges and web. The required root opening is 6 mm (1/4 inch) with a tolerance of plus 6 mm (1/4 inch) and minus 2 mm (1/16 inch).

The top of the pile being extended must be cut square with flat ends; the lower end of the extension, both flanges and web, must be beveled to a 45° angle (Figure B, Appendix A of this IM). The groove angle in the flat position is to be cut to a 45° included angle as shown in Figure C, Appendix 11-4 of the Construction Manual. The tolerance of a groove angle joint is $\pm 5^\circ$. The root face of the weld joints in Figures B and C shall be no greater than 2 mm (1/16 inch). When welding H piles, the web must be welded first.

E. Surface Roughness

Grinding will be required on all free hand oxygen cut joints to achieve the proper angles and surface smoothness. The roughness of oxygen cut surfaces shall not be greater than 25 micrometers (1000 micro-inches) as compared to a Surface Roughness Scale. The inspector should occasionally spot check joint preparation for roughness, prior to welding.

F. Pile Alignment

Sections of piles to be joined by butt welds shall be carefully aligned. Should the end of the pile to be extended be bent from driving, the bent portion of the pile shall be cut off. In aligning the piles for welding, the webs shall be brought into alignment first. If there is some slight dimensional variation due to fabrication, the pile extension shall be centered so that eccentricity of the flanges is reduced to a minimum.

G. Welder Certification

Welders qualified to work on Iowa DOT projects are qualified on 10 mm (3/8 inch) plates. The maximum thickness of plates that may be welded from one side under our normal certification is 19 mm (3/4 inch). If material thicker than 19 mm (3/4 inch) is to be welded, for example an HP 360 x 174 (HP 14 x 117), qualification tests on 25 mm (1 inch) plates will be required.

H. Welding Electrode and Preheat Requirements

The requirements regarding procedures for welding electrodes and preheating temperatures for the various types of steel piling are as follows:

1. Welding must be done with the same process (SMAW or FCAW) used for qualification.
2. If the operator has qualified on any of the steel permitted (ASTM A36 and A588), that same operator is qualified to weld on the other and on SAE 101 (Type I Pile) or ASTM A252 (Type II Pile).
3. A welder qualified for manual shielded metal-arc welding with an E 7018 electrode may also weld with E 7016 electrodes. For welding steel piles, E 7018 and E 7016 are preferred.

Identifying electrode numbers are as follows:

- The 70 designation shall be understood to mean the 70 series unless an alloy steel of higher strength is to be welded.
- The third digit indicates the position permitted. If the digit is "1," the electrode may be used for welding in any position. If "2," only the down hand position may be used.
- The fourth digit indicates the chemical make-up of the electrode coating. The digit 6 indicates low hydrogen potassium, and 8 a low hydrogen iron powder.

Preheating of the base metal means that the surfaces of the parts being welded, within 75 mm (3 inches) laterally and in advance of the welding, must be at or above the following prescribed temperature:

1. For A36 steel, Type V, piling up to and including 3/4 inch (19 mm) thickness – when welding with low hydrogen electrodes, the preheat temperature requirement is 50°F (10°C). For thickness of 3/4 inch (19 mm) and over, the preheat temperature requirement is 70°F (21°C).
2. For SAW 1010 steel, Type I, piling, the preheat requirement is the same as in No. 1.

-
3. For A252 steel, Type II, piling, the preheat temperature is 225°F (107°C) when welding with low hydrogen electrodes.

Welding when the ambient temperature is below 0°F (-18°C) is not permitted. In inclement or windy weather, suitable shielding must be provided to permit welding in the normal manner.

All electrodes having low hydrogen coverings shall be purchased in hermetically sealed containers or shall be dried for at least two hours between 450°F and 500°F (232°C and 260°C) before being used. Immediately after drying or removal from hermetically sealed containers, electrodes shall be kept in storage ovens of at least 250°F (121°C). Electrodes not used within four hours after removal from the drying or storage oven must be re-dried before use. For the ordinary field pile welding job, electrodes should be purchased in small packages, allowing for use within the prescribed time limit, unless provision for storage at 250°F (121°C) is made.

Preference of E 7016 and E 7018 electrodes for field welding may now be apparent. The digit 1 permits welding in all positions. These electrode coatings are low in hydrogen, permitting use on A36 and SAE 1010 steels without preheating the base metal unless the temperature is below 50°F (10°C). These electrodes are also required for making the prequalification test.

The restrictions and rules for preheating as outlined above cover the welding of all of our steel piling, since they apply to steel up to 3/4 inch (19 mm) thick. If welding is required on thicker plates, other special rules apply. In such a case, the Office of Materials should be contacted for assistance.

Electrodes that are allowed for Flux Cored Arc Welding are E60T-1, E60T-5, E60T-6, E60T-8, E70T-1, E70T-5, E70T-6 or E70T-8. When welding ASTM A588 steel, only the E70 series may be used.